

Gloucester Harbor Village Incremental Cost

30 Units

1.5% cost increase

Cost increases:

- Improved ventilation
- Added air sealing
- Thermally broken cladding attachment
- More construction verification
- Upgrade to triple glazed windows

